

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AS226
West
1/4-1/2
0.351 mi.
1851 ft.

MANHOLE 01470
CROPSEY AVE/HART PL
BROOKLYN, NY

Site 3 of 7 in cluster AS

NY Spills S105236229
N/A

Relative:
Higher

SPILLS:

Actual:
9 ft.

Name: MANHOLE 01470
Address: CROPSEY AVE/HART PL
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0108496 / 2003-07-28
Facility ID: 0108496
Facility Type: ER
DER Facility ID: 223651
Site ID: 205683
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2001-11-21
Investigator: KMFOLEY
Referred To: Not reported
Reported to Dept: 2001-11-22
CID: 397
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

Date Entered In Computer: 2001-11-22
Spill Record Last Update: 2003-07-28
Spiller Name: Not reported
Spiller Company: UNK
Spiller Address: UNK
Spiller Company: 999
Contact Name: CALLER
DEC Memo:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was FOLEY Con Ed e2mis #140360 Con Ed monthly status report from Feb 2002 indicates status code as pending safe access . 11/21/01 1347hrs - Michael Brillante # 30456 Splicer UG reports while doing maintenance inspections found 3 gallons unknown oil on 200 gallons water in MH01470. States no fire involved. No sewers or waterways affected. No private property affected. Sample taken and marked E priority - 24 hr deminimus program. Chain of custody # BB03117. Env. stop tag # 29480 placed. Clean up pending test results. No parking restrictions. # Update - Notified CIG @ 1417hrs - S. McKeever UPDATE 11-21-01 2120HRS CHEM LAB #01-11174-001 < 1 PPM LAZ # UPDATE : HUFFORD REPORTS CLEANUP COMPLETE DOUBLE WASHED WITH BULLDOG REMOVED ALL LIQUIDS NO SUMP IN STRUCTURE. LEFT TAG IN PLACE DUE TO APPROX. 30' OF OIL SOAKED ABSPESTOS ARC PROOFING. TAKING OFF 24 HOUR PROGRAM. CIG MCCARTHY NOTIFIED AT 0455HRS UPDATE*****11-24-01 13:45HRS ENV CREW PUMPED OUT WATER IN STRUCTURE AND U.G STATES THAT THERE IS APPROX 36' OF OIL SOAKED ASBESTOS ON TWO FEEDERS. THIS WILL BECOME AN OIL ABATMENT JOB. S.PACE 49874. UPDATE 02/11/02 18:53 HRS.... PER E. CORTES OF E.H.S. ASBESTOS ABATEMENT IS SCHEDULED FOR 2/28 - 3/1 OF 2002....DELAY WAS DUE TO A COMPUTER PROBLEM WITH ANTS AND WINDOWS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

2000. 2/28/02=1100HRS O.S. RASA U/G REPORTS
1-SAMPLE WAS TAKEN FROM OIL SOAKED CEMENT ARC-PROOF. CLEANUP IN
PROGRESS. WHEN COMPLETED TAG WILL REMAIN. PENDING TEST RESULTS.
UPDATE***** 2-28-02 11:45HRS B. TUDY REPORTS, DOUBLE
WASHED STRUCTURE WITH BIO GEN 760 BIO GEN, AND FOUND NO SUMP. PULLED
TAG# 29480 BUT WILL RETURN TO LOCATION TO INSTALL NEW TAG# 35859 AND
STILL WAITING FOR SAMPLE RESULTS OF CEMENT ARC-PROOFING (RESULTS
PERTAINING TO LEVEL OF ASBESTOS PRESENT.) S.PACE 49874.
UPDATE***** 3-1-02 18:45HRS A. WALKER (ENV OPS)
REPORTS, TAG# 35859 WAS REMOVED. JOB 100 COMPLETED. S.PACE "
"3 gallons on top of 200 gallons of water coned#140360 "

Remarks:

All Materials:

Site ID: 205683
Operable Unit ID: 846536
Operable Unit: 01
Material ID: 529744
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 3.00
Units: G
Recovered: 3.00
Oxygenate: Not reported